

LAN_B01_TT1_NF
417.90 NGF

LAN_B01_O6_NF
414.30 NGF

LAN_B01_O5_NF
410.70 NGF

LAN_B01_O4_NF
407.10 NGF

LAN_B01_O3_NF
403.50 NGF




LAN_B01_O2_NF
399.20 NGF

LAN_B01_O1_NF
394.90 NGF

LAN_B01_O0_NF
391.20 NGF

LAN_B01_SS1_NF
386.90 NGF

LAN_B01_VS_NF
385.10 NGF



LAN_B01_TT1_NF
417.90 NGF

LAN_B01_O6_NF
414.30 NGF

LAN_B01_O5_NF
410.70 NGF

LAN_B01_O4_NF
407.10 NGF

LAN_B01_O3_NF
403.50 NGF




LAN_B01_O2_NF
399.20 NGF

LAN_B01_O1_NF
394.90 NGF

LAN_B01_O0_NF
391.20 NGF

LAN_B01_SS1_NF
386.90 NGF

LAN_B01_VS_NF
383.10 NGF

[illegible]

LAN_B01_TT1_NF	417.90 NGF
LAN_B01_O6_NF	414.30 NGF
LAN_B01_O5_NF	410.70 NGF
LAN_B01_O4_NF	407.10 NGF
LAN_B01_O3_NF	403.50 NGF
LAN_B01_O2_NF	399.20 NGF
LAN_B01_O1_NF	384.90 NGF
LAN_B01_O0_NF	381.20 NGF
LAN_B01_SS1_NF	385.90 NGF
LAN_B01_VS_NF	

